



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	Area	Volume		corrective date
Type: Bradenhead		# 1		
Comment:				
Corrective Action:				Date:
Type: Plunger Lift		# 1		
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment		# 1		
Comment:	automation			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 203546 Type: WELL API Number: 001-09106 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>This is a follow up inspection for Document # 685100828                      At time of inspection corrective actions from previous inspection appear to have been addressed.                      At time of inspection location appears to be in compliance with COGCC rules.                      At time of inspection perception of location may have been distorted due to weather conditions.</p>	medinaj	03/16/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500966	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5098866">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5098866</a>