

RECEIVED  
DEC 20 1982



Use duplicate for Patented and Federal lands.  
Use in triplicate for State lands.

5. LEASE DESIGNATION & SERIAL NO.  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
Cheyenne State ✓  
9. WELL NO.  
1  
10. FIELD AND POOL, OR WILDCAT  
Wildcat ✓  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 12-T16S-R48W ✓  
12. COUNTY  
Cheyenne ✓  
13. STATE  
Colorado ✓

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL  GAS WELL  OTHER Dry hole, P&A  
2. NAME OF OPERATOR  
The Termo Company  
3. ADDRESS OF OPERATOR  
P. O. Box 2767, Long Beach, California 90801  
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface  
At proposed prod. zone  
14. PERMIT NO.  
821765  
15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
4216' GL, 4225' RKB

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF   
FRACTURE TREAT   
SHOOT OR ACIDIZE   
REPAIR WELL, (Other)   
PULL OR ALTER CASING   
MULTIPLE COMPLETE   
ABANDON   
CHANGE PLANS.

WATER SHUT-OFF   
FRACTURE TREATMENT   
SHOOTING OR ACIDIZING   
(Other) \_\_\_\_\_  
REPAIRING WELL   
ALTERING CASING   
ABANDONMENT\*   
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

18. Date of work 12-20-82 - proposed starting \* Must be accompanied by a cement verification report.

Perforations:  
5167'-5172' (.48") 11 holes  
4204'-4212' (.48") 17 holes  
4090'-4098' (.48") 17 holes

Proposal to plug and abandon:

1. Spot 15 sx. cement plug from 3990' to 4122'.
2. Cut off 5-1/2" casing at approximately 3550'.
3. Spot 35 sx. cement plug 50' in and 50' out of surface casing set at 306'.
4. Spot 10 sx. cement plug at surface.
5. Cut off 8-5/8" surface casing below plow level and weld on plate over 8-5/8" casing.

DWR	
FJP	
HHM	✓
JAM	✓
JJD	✓
RLS	
CGM	

19. I hereby certify that the foregoing is true and correct

SIGNED David E. Combs

TITLE Vice President

DATE 12/16/82

(This space for Federal or State office use)

APPROVED BY [Signature]  
CONDITIONS OF APPROVAL, IF ANY:

TITLE DIRECTOR  
O & G Cons. Comm.

DATE JAN 14 1983