

Inspection Photos

API: 071-09051

Operator: WAPITI OPERATING LLC

Inspection Date: 3/17/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09051 | Date: 3/17/2020

Inspection Photos



Photo 1. Facing south along the access road. The road has been graded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09051 | Date: 3/17/2020

Inspection Photos



Photo 2. It appears rock rip/rap was placed at the culvert outlet and is capturing sediment. This may need to be cleaned at and enlarged.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09051 | Date: 3/17/2020

Inspection Photos



Photo 3. The culvert inlet is filling in with sediment and needs to be cleaned out. BMP's may need to be installed up hill from the culvert to prevent sediment accumulation at culvert inlet.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09051 | Date: 3/17/2020

Inspection Photos



Photo 4. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09051 | Date: 3/17/2020