

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2020

Submitted Date:

03/19/2020

Document Number:

700400562

**FIELD INSPECTION FORM**

Loc ID 315097 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10654  
Name of Operator: LASSO OIL & GAS LLC  
Address: 3021 RIDGE RD #156  
City: ROCKWALL State: TX Zip: 75032

**Findings:**

3 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Freeman, Kris	254-717-0435	kfreeman@31operating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230249	WELL	PR	03/01/2019	GW	103-07908	CONTINENTAL 1-8	PR

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 3-18-2020 at approximately 16:45, inspector Rick Moran, conducted a routine inspection at Lasso Oil & Gas well Continental 1-8 in Rio Blanco county.

No corrective actions were identified.

This is a summary of inspection report 700400562.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 230249 Type: WELL API Number: 103-07908 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Blowdown      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective Action       Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Wildlife      Fencing Condition: Adequate

Comment:

Corrective Action       Date: \_\_\_\_\_

**Netting:**

Netting Type:      Netting Condition:

Comment:

Corrective Action       Date: \_\_\_\_\_

Anchor Trench Present:      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment:

Corrective Action       Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700400563	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5100813">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5100813</a>