

Inspection Photos

API: 071-09108

Operator: TIMBER CREEK OPERATING

Inspection Date: 3/19/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09108 | Date: 3/19/2020

Inspection Photos



Photo 1. Facing southwest along the access road. There are vehicle ruts along the road. The road needs to be graded and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09108 | Date: 3/19/2020

Inspection Photos



Photo 2. The culvert along the access road is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09108 | Date: 3/19/2020

Inspection Photos



Photo 3. There is erosion occurring on the side of the access road that needs to be repaired and stabilized. Arrow points to 4.5 ft. shovel for scale.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09108 | Date: 3/19/2020

Inspection Photos



Photo 4. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09108 | Date: 3/19/2020

Inspection Photos



Photo 5. The oil on the engine skid has been cleaned up since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09108 | Date: 3/19/2020

Inspection Photos



Photo 6. The oil on the engine skid has been cleaned up since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09108 | Date: 3/19/2020

Inspection Photos



Photo 7. There is oil stained soil approximately 1'x3' area that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09108 | Date: 3/19/2020