

Inspection Photos

API: 071-09853

Operator: TIMBER CREEK OPERATING

Inspection Date: 3/19/2020



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 3/19/2020

Inspection Photos



Photo 1. The culvert along the main lease road road is filled in with sediment.
Lat/Long:37.13931,-104.91829.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 3/19/2020

Inspection Photos



Photo 2. Facing northwest along the main lease road ascending the hill. There are vehicle ruts along the road. The road needs to be graded and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 3/19/2020

Inspection Photos



Photo 3. Another culvert along the main lease road is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 3/19/2020

Inspection Photos



Photo 4. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 3/19/2020

Inspection Photos



Photo 5. The 200 barrel open top tank does not have secondary containment installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 3/19/2020

Inspection Photos



Photo 6. The exhaust pipe is laying on the ground at the compressor. The exhaust muffler is very loud. Maintenance is needed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 3/19/2020

Inspection Photos



Photo 7. Facing east toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09853 | Date: 3/19/2020