

Inspection Photos

API: 071-09236

Operator: TIMBER CREEK OPERATING

Inspection Date: 3/19/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09236 | Date: 3/19/2020

Inspection Photos



Photo 1. The culvert along the main lease road ascending the hill to the location is filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 3/19/2020

Inspection Photos



Photo 2. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 3/19/2020

Inspection Photos



Photo 3. There is oil stained soil around the engine skid that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 3/19/2020

Inspection Photos



Photo 4. The sound wall is laying on the ground and the standing walls have no use. Unused equipment needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 3/19/2020

Inspection Photos



Photo 5. Well sign is posted at the meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 3/19/2020

Inspection Photos



Photo 6. There is erosion occurring down the road as it ascends to the top of the hill. Approx. Lat/Long:37.12287,-104.95893.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 3/19/2020