

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2020

Submitted Date:

03/20/2020

Document Number:

693200578

**FIELD INSPECTION FORM**

Loc ID 335657 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rcowden@caerusoilandgas.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281383	WELL	PR	11/11/2006	GW	045-11437	N.PARACHUTE EF 15D C28 595	EG
281385	WELL	PR	11/16/2005	GW	045-11438	N.PARACHUTE EF 11D C28 595	EG
281386	WELL	PR	11/22/2006	GW	045-11439	N.PARACHUTE EF03D C28 595	EG
281413	WELL	PR	02/01/2011	GW	045-11455	N.PARACHUTE EF15B C28 595	EG
281414	WELL	PR	11/30/2006	GW	045-11456	N. PARACHUTE EF14D C28 595	EG
281415	WELL	PR	02/01/2011	GW	045-11457	N. PARACHUTE EF11B C28 595	EG
281416	WELL	PR	02/01/2011	GW	045-11458	N.PARACHUTE EF10B C28 595	EG
281417	WELL	PR	11/17/2005	GW	045-11459	N.PARACHUTE EF06D C28 595	EG
282913	WELL	PR	02/13/2007	GW	045-11874	N. PARACHUTE EF03B C28 595	EG
282914	WELL	PR	02/12/2007	GW	045-11873	N. PARACHUTE EF11B-21C28 595	EG
282915	WELL	PR	02/12/2007	GW	045-11875	N. PARACHUTE EF 10B-21 C28 5	EG
282916	WELL	PR	02/01/2011	GW	045-11872	N.PARACHUTE EF 14B C28 595	EG
282917	WELL	PR	02/13/2007	GW	045-11871	N. PARACHUTE EF 13B C28 595	EG

282918	WELL	PR	07/01/2019	GW	045-11870	N.PARACHUTE EF 12B C28 595	EG
282919	WELL	PR	01/01/2018	GW	045-11869	N. PARACHUTE EF11D21 C28 595	EG
282920	WELL	PR	02/01/2014	GW	045-11868	N. PARACHUTE EF14D21 C28 595	EG
282921	WELL	PR	02/01/2011	GW	045-11867	N. PARACHUTE EF09D C28 595	EG
282922	WELL	PR	02/13/2007	GW	045-11865	N. PARACHUTE EF 13D C28 595	EG
283130	WELL	PR	02/12/2007	GW	045-11896	N. PARACHUTE EF06B C28 595	EG
283131	WELL	PR	02/13/2007	GW	045-11895	N. PARACHUTE EF 12D C28 595	EG
299174	WELL	PR	12/24/2010	GW	045-17588	N. Parachute EF15B-21 C28 59	EG
299178	WELL	PR	12/27/2010	GW	045-17589	N. Parachute EF10D-21 C28 59	EG
299182	WELL	PR	09/30/2010	GW	045-17593	N. Parachute EF15C-28 C28 59	EG
299183	WELL	PR	12/27/2010	GW	045-17594	N. PARACHUTE EF10D-28 C28595	EG
299184	WELL	PR	02/14/2011	GW	045-17595	N. Parachute EF10C-28 C28 59	EG
299187	WELL	PR	01/28/2011	GW	045-17598	N. Parachute EF15A-28 C28 59	EG
299190	WELL	PR	10/03/2010	GW	045-17601	N. Parachute EF10A-21 C28 59	EG
299191	WELL	PR	10/03/2010	GW	045-17602	N. Parachute EF10C-21 C28 59	EG

**General Comment:**

Engineering Integrity Inspection performed on March 20, 2020

Failed flowline was discovered before it released enough fluid to become a reportable spill

## Inspected Facilities

Facility ID: 281383 Type: WELL API Number: 045-11437 Status: PR Insp. Status: EG

## Flowline

#1 Type: Well Site 1 of Lines

## Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel  
 Variance: No Age: 1-5 Yrs Contents: Multiphase

## Integrity Summary

Failures: Other Spills: No Repairs Made: Yes  
 Coatings: Yes External H2S: No Cathodic Protection: No

## Pressure Testing

Witnessed: No Test Result: Pass Charted: Yes

## COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Provide pressure test results, performed before returning back to in service, Via FIRR and email to Western Integrity inspector

Provide Root Cause when information becomes available. Via Form 4 and email to Western Integrity inspector

Corrective Action:

Date:

Facility ID: 281385 Type: WELL API Number: 045-11438 Status: PR Insp. Status: EG

Facility ID: 281386 Type: WELL API Number: 045-11439 Status: PR Insp. Status: EG

Facility ID: 281413 Type: WELL API Number: 045-11455 Status: PR Insp. Status: EG

Facility ID: 281414 Type: WELL API Number: 045-11456 Status: PR Insp. Status: EG

Facility ID: 281415 Type: WELL API Number: 045-11457 Status: PR Insp. Status: EG

Facility ID: 281416 Type: WELL API Number: 045-11458 Status: PR Insp. Status: EG

Facility ID: 281417 Type: WELL API Number: 045-11459 Status: PR Insp. Status: EG

Facility ID: 282913 Type: WELL API Number: 045-11874 Status: PR Insp. Status: EG

Facility ID: 282914 Type: WELL API Number: 045-11873 Status: PR Insp. Status: EG

Facility ID: 282915 Type: WELL API Number: 045-11875 Status: PR Insp. Status: EG

Facility ID: 282916 Type: WELL API Number: 045-11872 Status: PR Insp. Status: EG

Facility ID: <u>282917</u>	Type: <u>WELL</u>	API Number: <u>045-11871</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>282918</u>	Type: <u>WELL</u>	API Number: <u>045-11870</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>282919</u>	Type: <u>WELL</u>	API Number: <u>045-11869</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>282920</u>	Type: <u>WELL</u>	API Number: <u>045-11868</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>282921</u>	Type: <u>WELL</u>	API Number: <u>045-11867</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>282922</u>	Type: <u>WELL</u>	API Number: <u>045-11865</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>283130</u>	Type: <u>WELL</u>	API Number: <u>045-11896</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>283131</u>	Type: <u>WELL</u>	API Number: <u>045-11895</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>299174</u>	Type: <u>WELL</u>	API Number: <u>045-17588</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>299178</u>	Type: <u>WELL</u>	API Number: <u>045-17589</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>299182</u>	Type: <u>WELL</u>	API Number: <u>045-17593</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>299183</u>	Type: <u>WELL</u>	API Number: <u>045-17594</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>299184</u>	Type: <u>WELL</u>	API Number: <u>045-17595</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>299187</u>	Type: <u>WELL</u>	API Number: <u>045-17598</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>299190</u>	Type: <u>WELL</u>	API Number: <u>045-17601</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>299191</u>	Type: <u>WELL</u>	API Number: <u>045-17602</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200579	Repair photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5101612">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5101612</a>