

Inspection Photos

Operator: Hilcorp Energy
API#: 067-07798
Date: 3/18/2020



Photo 1. View of the project area from the northwestern corner entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing here, largely with smooth brome and mixed wheatgrasses.



Photo 3. View of the surrounding reference area comprised of smooth brome dominated grass field with patches of gambel oak.