

Inspection Photos  
Operator: Hilcorp Energy  
API#: 067-06581  
Date: 3/18/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing here in a grazed condition similar to reference area.



Photo 3. View of erosional channel approximately 2 feet wide and 1 foot deep, forming within the southwestern corner of the project area. Hard hat in place for scale reference.



Photo 4. View of trailer parked on well pad, needs to be removed.



Photo 5. View of reference area, comprised of grass field in a grazed vegetative condition.