

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2020

Submitted Date:

03/23/2020

Document Number:

697000881

FIELD INSPECTION FORM

Loc ID 307117 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 95233
Name of Operator: WELLINGTON OPERATING COMPANY
Address: 6065 S QUEBEC ST STE 200
City: CENTENNIAL State: CO Zip: 80111

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
Gracey, Cameron		graceyservices@msn.com	
Pomeroy, Bradley		pomoco@msn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216904	WELL	PR	09/27/1999	OW	069-06091	W F MUDDY UT/ELDER 32-4	PR

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:
 Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type PUMP JACK		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Type	Area	Volume			corrective date
Type: Bradenhead	# 1				
Comment:	Bradenhead valve is exposed at surface.				
Corrective Action:				Date:	
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	
Type: Flow Line	# 1				
Comment:					
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:	Natural gas engine				
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 216904 Type: WELL API Number: 069-06091 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Flowline

#1 Type:

of Lines

Flowline Description

Flowline Type:

Size:

Material:

Variance:

Age:

Contents:

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed:

Test Result:

Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation

1102. Operations, Maintenance, and Repair

1103. Abandonment

Comment:

All corrective actions noted in prior inspection document #690101577 have been addressed.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697000882	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5102748