

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/24/2020

Submitted Date:

03/24/2020

Document Number:

696301614

FIELD INSPECTION FORM

Loc ID 433076	Inspector Name: PETRIE, ERICA	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 100322 Name of Operator: NOBLE ENERGY INC Address: 1001 NOBLE ENERGY WAY City: HOUSTON State: TX Zip: 77070				Findings: 22 Number of Comments 5 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433062	WELL	PR	12/13/2013	OW	123-37448	Rohn State LD04-63HN	PR
433066	WELL	PR	12/10/2013	OW	123-37451	Rohn State LD04-65-1HN	PR
433068	WELL	PR	12/30/2014	OW	123-37453	Rohn State LD03-63HN	PR
433075	WELL	PR	01/03/2015	OW	123-37457	Rohn State LD03-64HN	PR
433081	WELL	PR	12/29/2014	OW	123-37462	Rohn State LD03-64-1HN	PR
433083	WELL	PR	12/04/2013	OW	123-37463	Rohn State LD04-64HN	PR
433091	WELL	PR	12/27/2014	OW	123-37467	Rohn State LD03-65-1HN	PR
433109	WELL	PR	12/04/2013	OW	123-37482	Rohn State LD04-64-1HN	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical Tank labels on Westside Wellheads have faded or are missing. See photos		
Corrective Action:	Comply with Rule 210.d.	Date:	04/24/2020
Type	TANK LABELS/PLACARDS		
Comment:	Water tanks south of Oil Tanks missing signage. Water Tank at Gas Meters missing signage		
Corrective Action:	Comply with Rule 210.d.	Date:	04/24/2020
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused Automation wires at South Gas Lift Meter house, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	04/24/2020
Type	STORAGE OF SUPL		
Comment:	Unused Chemical Tank and Stands, North of Maintenance Tank, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	04/24/2020
Type	STORAGE OF SUPL		
Comment:	Unused Stairs west of Crude Oil Tanks, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	04/24/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		

Comment: Panels					
Corrective Action:				Date:	

<u>Equipment:</u>			corrective date		
Type: Gas Meter Run	# 20				
Comment:					
Corrective Action:		Date:			
Type: VRT	# 3				
Comment:					
Corrective Action:		Date:			
Type: Compressor	# 2				
Comment:					
Corrective Action:		Date:			
Type: Plunger Lift	# 8				
Comment:					
Corrective Action:		Date:			
Type: Horizontal Heated Separator	# 12				
Comment:					
Corrective Action:		Date:			
Type: LACT	# 1				
Comment:					
Corrective Action:		Date:			
Type: Bradenhead	# 8				
Comment: Appear to be plumbed to Surface					
Corrective Action:		Date:			
Type: Other	#				
Comment: 23 Sand Traps					
Corrective Action:		Date:			
Type: VRU	# 2				
Comment:					
Corrective Action:		Date:			
Type: Emission Control Device	# 9				
Comment:					
Corrective Action:		Date:			
Type: Vertical Separator	# 5				
Comment:					
Corrective Action:		Date:			

<u>Tanks and Berms:</u>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL		OTHER	STEEL AST		40.776630,-103.860710
Comment: 24 Tanks					

Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity) 750 BBLS							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Metal	Adequate		Walls Sufficient		Base Sufficient		Adequate
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type		Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST			40.777520,-103.862110	
Comment: Maintenance Tank							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Earth	Adequate		Walls Sufficient		Base Sufficient		Adequate
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type		Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	BV CONCRETE			,	
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity) 60 BBLS							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Comment: Shares berm with the Crude Oil Tanks							
Corrective Action:						Date:	
Contents	#	Capacity	Type		Tank ID	SE GPS	

PRODUCED WATER	12	500 BBLs	FIBERGLASS AST		40.776830,-103.861050	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No						
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	433062	Type:	WELL	API Number:	123-37448	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	433066	Type:	WELL	API Number:	123-37451	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433068	Type:	WELL	API Number:	123-37453	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433075	Type:	WELL	API Number:	123-37457	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433081	Type:	WELL	API Number:	123-37462	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433083	Type:	WELL	API Number:	123-37463	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433091	Type:	WELL	API Number:	123-37467	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	433109	Type:	WELL	API Number:	123-37482	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 03/19/2020 at approximately 12:37, I, Inspector Erica Petrie, conducted a Field Inspection at Noble Energy INC. Rohn State LD03-65-1HN Multi-PAD and Tank Battery, Location ID #433076 in Weld County, Colorado.</p> <p>While there, I observed Production Operations. Winter Conditions, snow covered ground at the time of this Inspection.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Chemical Container Labels at West wellheads have faded or are missing. See photos. Comply with Rule 210.d. Corrective Action date 04.24.2020</p> <p>Unused Automation Wires at South Gas Lift Meter houses. See photos. Comply with Rule 603.f. Corrective Action date 04.24.2020</p> <p>Unused Walkover Stairs North of Maintenance Tank. See photos. Comply with Rule 603.f. Corrective Action date 04.24.2020</p> <p>Produced Water Tanks at Gas Meter and South of Crude Oil Tanks are missing Content, Capacity and NFPA labels. See photos. Comply with Rule 210.c. and 210.d. Corrective Action date 04.24.2020</p> <p>Unused Chemical Container/Tank and Stands. See photos. Comply with Rule 603.f. Corrective Action date 04.24.2020</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petrie	03/24/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696301615	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5103573