

Inspection Photos

API: 071-09420

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/23/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 3/23/2020

Inspection Photos



Photo 1. The pig launcher receiver remains along the main access road. No other PR wells remain west along the road. Lat/Long: 37.25975,-104.97719.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 3/23/2020

Inspection Photos



Photo 2. Facing west along the main access road. This road appears to be pre-existing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 3/23/2020

Inspection Photos



Photo 3. There is a pipe riser that remains along the main access road at Lat/Long:37.26190,-104.98726.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 3/23/2020

Inspection Photos



Photo 4. Facing northwest at the beginning of the access road (above red line). This road was not pre-existing and has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 3/23/2020

Inspection Photos



Photo 5. Facing northwest toward the location. The location has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 3/23/2020

Inspection Photos



Photo 6. Facing northwest toward the location. A connex storage container is placed on location. The center of the location is bare of vegetation and gravel remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 3/23/2020

Inspection Photos



Photo 7. Facing northwest toward the location. A connex storage container is placed on location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 3/23/2020