

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2020

Submitted Date:

03/24/2020

Document Number:

693200580**FIELD INSPECTION FORM**Loc ID 335574 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rcowden@caerusoilandgas.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282338	WELL	PR	08/01/2008	GW	045-11745	N. PARACHUTE EF11B D27 595	EG

**General Comment:**

Engineering Integrity Inspection performed on March 20, 2020.

Flowline was repaired and put back into service prior to inspection

**Inspected Facilities**

Facility ID: 282338 Type: WELL API Number: 045-11745 Status: PR Insp. Status: EG

**Flowline**

#1	Type: Dump Line	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: 2" Material: Carbon Steel  
 Variance: No Age: 1-5 Yrs Contents: Multiphase

Integrity Summary

Failures: Spills: Repairs Made: Yes  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: No Test Result: In Process Charted: No

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Provide pressure test results, performed before returning back to in service, Via FIRR and email to Western Integrity inspector

Provide Root Cause when information becomes available. Via Form 4 and email to Western Integrity inspector

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200582	Repaired flowline	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5103952">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5103952</a>