

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2020

Submitted Date:

03/25/2020

Document Number:

699101278

FIELD INSPECTION FORM

Loc ID 305389 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------------------------------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 277102 | WELL | PR | 09/01/2016 | GW | 123-22899 | GUTTERSEN D33-10 | TA |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | WEEDS | | |
| Comment: | Weeds grown in tank battery need to be removed for good housekeeping. See attached photos | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 04/03/2020 |
| Type | TRASH | | |
| Comment: | Two locations of trash in tank battery need to be removed for good housekeeping. See attached photos. | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 04/03/2020 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------------|-------|--|
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | Barbwire | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Barbwire | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Barbwire | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----------------------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 2 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Appears to be plumbed to surface. | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|--|----------|-------------|---------|--------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | OTHER | BV CONCRETE | | , | |
| Comment: | Shares containment with crude oil tanks. | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|--------|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | 48 BBL | |
| Other (Type) | | |

Berms

| | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | Date: | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CRUDE OIL | 2 | 300 BBLS | STEEL AST | | 40.178160,-104.553610 | |
| Comment: | | | | | | |

| | | | |
|--------------------|----------|---------------------|-------------|
| Corrective Action: | | Date: | |
| Paint | | | |
| Condition | Adequate | | |
| Other (Content) | | | |
| Other (Capacity) | | | |
| Other (Type) | | | |
| Berms | | | |
| Type | Capacity | Permeability (Wall) | Maintenance |
| Earth | Adequate | Walls Sufficient | Adequate |
| Comment: | | | |
| Corrective Action: | Date: | | |
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | Date: | | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | Date: | | |

Inspected FacilitiesFacility ID: 277102 Type: WELL API Number: 123-22899 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: T/A, has blue "T/A" Variance Tag.

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary

On Wednesday 3/25/20 at approximately 0821 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Guttarsen D33-10 of Noble Energy, at Location # 305389 in Weld County, Colorado.

During this inspection the following possible compliance issues were observed:

Weeds grown in tank battery need to be removed for good housekeeping. Comply with Rule 603.f. With a corrective action date of 4/3/20.

Trash in two spots in tank battery need to be removed for good housekeeping. Comply with Rule 603.f. With a corrective action date of 4/3/20.

See attached photos.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Continuing education inspections

burnsa

03/25/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 699101279 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5104283 |