

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25SESW

Location ID: 312507



Photo #0836 from entrance to location



Photo #0835 Access road has not been maintained.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25SESW

Location ID: 312507



Photo #0837 Multiple flow line risers not LO/TO.



Photo #0838 Multiple flow line risers not LO/TO.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25SESW

Location ID: 312507



Photo #0839 Multiple flow line risers not LO/TO.



Photo #0840 Multiple flow line risers not LO/TO.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25SESW

Location ID: 312507



Photo #0841 Multiple places with debris on location.