

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2020

Submitted Date:

03/25/2020

Document Number:

699800782

FIELD INSPECTION FORM

Loc ID 312470 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 11 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Jordan, Reid	970-563-4000	maralextechjr@gmail.com	Ignacio
Graves, Jim	(970) 858-8550	mrinc20@qwestoffice.net	Operations Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221711	WELL	PR	09/01/1995	GW	077-08313	FEDERAL 30-3	PR

General Comment:

[COGCC Inspection Report Summary](#)
On Wednesday 3/25/20 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC FEDERAL-68S97W /30SWSW, Location #312470 in Mesa County Colorado.
Refer to document #696600422 inspection conducted on 8/1/19. Not all previous corrective actions have been completed. While there, I observed normal production operations.
During this inspection the following possible compliance issues were observed: Access road has not been maintained. See photo #0825 with a previous corrective action date of 9/2/19. Debris around equipment and inside pit. See photo #0818, #0819 and #0823 with a corrective action date of 4/1/20. Multiple places with unused equipment on location. See photo #0821 and #0822 with a previous corrective action date of 9/3/19. Flow line risers not LO/TO. See photo #0820 with a corrective action date of 3/26/20. No pit permit on file. With a corrective action date of 4/9/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:	Access road has not been maintained. See photo #0825		
Corrective Action:	Repair and maintain lease road.	Date:	09/02/2019
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	No tank battery on location.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Flow line risers not LO/TO. See photo #0820		
Corrective Action:	Flow line risers not LO/TO or marked are considered unused equipment. Properly lock out and tag out flow line.	Date:	03/26/2020
Type	STORAGE OF SUPL		
Comment:	Multiple places with unused equipment on location. See photo #0821 and #0822		
Corrective Action:	Production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove all unused equipment from location.	Date:	09/03/2019
Type	DEBRIS		
Comment:	Debris around equipment and inside pit. See photo #0818, #0819 and #0823		
Corrective Action:	Production facilities, shall be kept free of rubbish. Remove all debris from location.	Date:	04/01/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:	_____		
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type:	Horizontal Heated Separator	# 1	corrective date
Comment:			
Corrective Action:			Date:
Type:	Plunger Lift	# 1	
Comment:			
Corrective Action:			Date:
Type:	Bird Protectors	# 2	

Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 221711 Type: WELL API Number: 077-08313 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Gravel						
		Ditches				
		Compaction				
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown

Lined: NO

Pit ID: _____

Lat: _____

Long: _____

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type: _____

Liner Condition: _____

Comment: No pit permit on record.

Corrective Action

Submit an eForm 15 Pit Report to update COGCC records with current information.

Date: 04/09/2020

Fencing:

Fencing Type: Livestock

Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: Mesh

Netting Condition: Good

Comment:

Corrective

Date: _____

Anchor Trench Present: NO

Oil Accumulation: NO

2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699800783	Photos for Insp. #699800782	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5105289