

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2020

Submitted Date:

03/26/2020

Document Number:

697000906**FIELD INSPECTION FORM**Loc ID 329435 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249546	WELL	SI	10/01/2019	OW	123-17349	SPAUR O 7-8	SI
417710	WELL	PR	05/01/2019	OW	123-31726	SPAUR 17-7	PR
417712	WELL	PR	07/01/2018	OW	123-31728	SPAUR 24-7	PR
417715	WELL	PR	07/01/2018	OW	123-31731	SPAUR 21-7	PR
417719	WELL	PR	07/01/2018	OW	123-31733	SPAUR 41-7	PR

General Comment:[FIRR document #402325364](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	x 5		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Barbed wire topped chainlink		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire topped chainlink		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Barbed wire topped chainlink x 5		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barbed wire topped chainlink		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:	Pilot is on		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		

Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter calibration card noted in prior inspection document #697000571 has been updated. See attached photos.		
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	Bradenhead valves are exposed at surface.		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Automation array and ECD scrubber		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:	210 bbls. Produced water vault is anchored.				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:			Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	OTHER	STEEL AST		,
Comment:	315 bbls				
Corrective Action:			Date:		

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 249546 Type: WELL API Number: 123-17349 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date:

Facility ID: 417710 Type: WELL API Number: 123-31726 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: Date:

Facility ID: 417712 Type: WELL API Number: 123-31728 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: Date:

Facility ID: 417715 Type: WELL API Number: 123-31731 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: Date:

Facility ID: 417719 Type: WELL API Number: 123-31733 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697000907	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5106055