

Banta Ridge 16-19-1-103

API: 05-103-10311

Inspection: 700400672



39.95126, -108.99257, 6001.0ft, 83°

03/26/2020 03:14:18 PM




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

Banta Ridge 16-19-1-103

API: 05-103-10311

Inspection: 700400672



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 2. Well head.



Banta Ridge 16-19-1-103

API: 05-103-10311

Inspection: 700400672



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Meter building & separator.**

Banta Ridge 16-19-1-103

API: 05-103-10311

Inspection: 700400672



39.95109, -108.9919, 5996.8ft, 247°

03/26/2020 03:16:18 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources


**Photo 4. Tanks.**



Banta Ridge 16-19-1-103

API: 05-103-10311

Inspection: 700400672



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 5. Leaking tank.

Banta Ridge 16-19-1-103

API: 05-103-10311

Inspection: 700400672



39.95109, -108.99208, 6000.6ft, 168°

03/26/2020 03:17:41 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 6. Leaking tank flange.**