

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402352750

Date Received:  
03/27/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 95520

Name of Operator: WESCO OPERATING INC

Address: 120 S DURBIN STREET

City: CASPER State: WY Zip: 82602

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Kirkwood, Tom

307-577-5328

tomk@kirkwoodcompanies.com

Kerr, Scott

307-577-5336

scottk@kirkwoodcompanies.com

Weinert, Dave

(307) 577-5329

davew@kirkwoodcompanies.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688000394

Inspection Date: 03/02/2020

FIR Submit Date: 03/10/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: WESCO OPERATING INC

Company Number: 95520

Address: 120 S DURBIN STREET

City: CASPER State: WY Zip: 82602

LOCATION - Location ID: 317096

Location Name: RUDNIK-63S51W Number: 27NWSE County: \_\_\_\_\_

Qtrqr: NWSE Sec: 27 Twp: 3S Range: 51W Meridian: 6

Latitude: 39.762550 Longitude: -103.073940

FACILITY - API Number: 05-121-00 Facility ID: 317096

Facility Name: RUDNIK-63S51W Number: 27NWSE

Qtrqr: NWSE Sec: 27 Twp: 3S Range: 51W Meridian: 6

Latitude: 39.762550 Longitude: -103.073940

CORRECTIVE ACTIONS:

1 CA# 137114

Corrective Action: Provide a FIRR detailing what the above noted impacts were caused by (providing documentation that the release was less than 5bbl) or submit a Form 19.

Date: 03/27/2020

Response: CA COMPLETED

Date of Completion: 03/26/2020

Operator Comment: Wesco HSE staff spoke with Luke Cromley, the contract pumper for this location concerning the impacts discussed in the inspection report. Luke said that there was a small leak in the injection system on an 1/8 inch copper line that runs between the murphy switch and the produced water tank. The leak volume was

approxiamtely 3/4 barrel, all in containment. The leak occurred on February 18th, 2020. When the line was repaired and other fittings on the injection system were replaced and replumbed, a small amount (approxiamtely 1 barrel) of produced water was released within containment. The scrape marks on the inside of the berm are from a backhoe that was used to work on the injection system. Luke said there was snowmelt already present inside the berm at the time of the spill. The shallow trench observed leading out from the injection building during the inspection was from the electricians installing a lease kill switch. The wet area around the base of the produced water tank is from a natural collection of snowmelt. The observed staining around the concrete vault was the result of an overflow resulting from the draining of lines during the repairs discussed above. Luke said that he was present at the location when the overflow occurred and that approxiamtely 10 gallons was the volume that overflowed. Luke said that there was a vac truck present when the overflow occurred and that the vault was immediately emptied and the fluids placed back into the water tank. See also attached photos (3) documenting the site conditions on March 17th, 2020.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 137115

Corrective Action: Submit the laboratory analytical data and the requested sample location drawing on a  
suppelemental Form 27.

Date: 03/27/2020

Response: CA COMPLETED

Date of Completion: 03/27/2020

Operator Comment: Form 27s submitted. Most of this information was previously submitted in 2015 as documented on the attached emails from Scott Kerr to Annie Eckman dated 1/2/2015 and from Scott Kerr to Rob Young dated 12/28/2015.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: See Wesco comments for each item.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dave Weinert

Signed: \_\_\_\_\_

Title: HSE Coordinator

Date: 3/27/2020 11:36:42 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402353888	email
402353889	email
402354229	photo
402354231	photo
402354232	photo

Total Attach: 5 Files