

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2020

Submitted Date:

03/29/2020

Document Number:

688307474

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
 320790 _____ Sherman, Susan _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10646
 Name of Operator: AXIS EXPLORATION LLC
 Address: 370 17TH ST SUITE 5300
 City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Antonioli, Philip	720-345-4603	PAntonioli@extractionog.com	
Dunning, Michael	303 396-6040	mdunning@extractionog.com	
Extraction	720-370-5540	COGCCInspections@extracti onog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204945	WELL	SI	06/01/2018	GW	005-07080	MURPHY 24-17	PA

General Comment:

PA Inspection, after surface cement pumped
 Cement -4" BGS, location clean, truck removing returns tank, tubing on location on a trailer and tank battery equipment remains.

Inspected Facilities

Facility ID: 204945 Type: WELL API Number: 005-07080 Status: SI Insp. Status: PA

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688307545	Axis Exploration Murphy 24-17	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5108859