

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/17/2020

Submitted Date:

03/23/2020

Document Number:

699700115

**FIELD INSPECTION FORM**

Loc ID 335193 Inspector Name: Heil, John On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Fischer, Alex		alex.fischer@state.co.us	
Gardner, Mike		mgardner@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437202	SPILL OR RELEASE	AC	05/29/2014		-	SPILL/RELEASE POINT	EI

**General Comment:**

On March 17, 2020, COGCC Environmental Staff (John Heil) conducted an environmental field inspection of TEP ROCKY MOUNTAIN LLC (TEP operator #96850) Location ID 335193 RMV 152-22 Pad Spill ID 437202.

**Inspected Facilities**

Facility ID: 437202 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

## Environmental

**Spills/Releases:**Type of Spill: CONDENSATE

Estimated Spill Volume: \_\_\_\_\_

Comment: 5/14/2014 TEP (Formally WPX) submitted a F19 Initial when a corroded condensate tank released fluids into an earthen secondary containment structure.

Corrective Action: Operator shall provide the status and update of Spill/Release 437202 on a Supplemental F19.

Date: 05/08/2020Reportable: YES

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402349588	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5102474">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5102474</a>
699700116	20200317 Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5102472">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5102472</a>