

Inspection Photos

Operator: Hilcorp Energy
API#: 067-08186
Date: 3/24/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern edge facing southward. Revegetation I progressing with mixed wheatgrasses, rubber rabbitbrush, sagebrush, and fourwing saltbush.



Photo 3. View of Russian knapweeds within the northeastern project area. Approximately 150 individuals observed.



Photo 4. View of saltcedar tree (noxious weed) at entrance to access road. Needs to be removed.



Photo 5. View of reference area vegetation comprised of sagebrush dominated shrubland with native grasses, forbs, and sub-shrubs in the understory. Pinyon and junipers are largely on slopes.