

Inspection Photos
Location Name: Sanchez #3
API: 05-067-05341



Sanchez #3 access road.



Electrical supply to location.

Inspection Photos
Location Name: Sanchez #3
API: 05-067-05341



Location photo looking west from secondary containment berm for AST.



Location photo of PA well pad.

Inspection Photos
Location Name: Sanchez #3
API: 05-067-05341



Steel pipe and other debris on location.



Steel pipe protruding from secondary containment berm.

Inspection Photos
Location Name: Sanchez #3
API: 05-067-05341




Crude oil AST, marked empty by COGCC field inspector.



Oil stained soil beneath load out valve.

Inspection Photos
Location Name: Sanchez #3
API: 05-067-05341



Stained area beneath compromised seam along bottom of AST.



Flow line to AST.