

Inspection Photos

Operator: Hilcorp Energy
API#: 067-07243
Date: 3/24/2020




Photo 1. View of the project area from the former well pad entrance facing center. Dense, dried vegetation on the well pad is largely Russian thistle debris.



Photo 2. View of electrical equipment that remains within the western project area. Closeup in lower left inset shows exposed electrical wiring.



Photo 3. View of erosional rilling (approximately 1 foot wide and deep) within the northwestern project area facing up-slope (southward).



Photo 4. View of the northern fill slope facing eastward from the northwestern corner of the well pad.



Photo 5. View from the beginning of Transect 1, within the project disturbance area facing westward. No desirable vegetation was detected along vegetation transect.



Photo 6. Birdseye view of midpoint along the vegetation Transect. Observable vegetation is all weed debris from previous growing seasons-largely Russian thistle and bindweed.



Photo 7. View of reference area vegetation, largely comprised of open sagebrush shrubland with native perennial grasses and forbs.