

## Inspection Photos

Location Name: VPR C NO. 75 CA DATE 4-30-20

API#: 05-071-07397

INSP. #: 695102463



**PHOTO 1: LOCATION**

**PHOTO 2: WELL SIGN**

## Inspection Photos

Location Name: VPR C NO. 75 CA DATE 4-30-20

API#: 05-071-07397

INSP. #: 695102463



**PHOTO 3: AREA OF IMPACTED SOIL APPEARS TO BE OIL FROM COMPRESSOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-30-20.**

**PHOTO 4: AREA OF IMPACTED SOIL APPEARS TO BE OIL FROM POLISH ROD LUBRICATOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-30-20.**