

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2020

Submitted Date:

03/31/2020

Document Number:

696201118

**FIELD INSPECTION FORM**Loc ID 314813 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 74740

Name of Operator: RIO MESA RESOURCES INC

Address: P.O. BOX 984

City: RANGELY State: CO Zip: 81648

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		hayespetro@centurytel.net	
		craig.burger@state.co.us	
		rick.moran@state.co.us	
		hayespetroleum@gmail.com	
Lutz, Deborah		debbie.lutz@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229646	WELL	PR	02/01/2019	OW	103-07303	GETTY-PAN AM 19-A	RI

**General Comment:**

On 3/30/2020, Reclamation Specialist Trujillo conducted a followup interim reclamation and stormwater inspection at RIO MESA RESOURCES INC's Getty-Pan AM #19-A location in Rio Blanco County, Colorado.

This inspection is to document compliance for the following corrective actions from inspection #696201101:  
1002.f: Chemicals within containment

It was documented that the fluids/chemicals observed in inspection #696201101 have not been removed.

Inspection #696201101 also required Operator to comply with Rule 907.e to clean/remediate/remove stained soils from areas adjacent to the wellhead by 4/1/2020; Corrective action remains applicable.

The following alleged compliance issues were also observed during this inspection:  
603.f: Trash debris/Unused equipment observed on Location and interim areas

Refer to the "Location" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Various trash debris/unused equipment were observed on the Locaiton; Trash debris (oily rags)/cable were observed on western areas of the Location; Portions of the utility pole have been cut above the electric box and left on interim areas of the southeast end of the Location; The anchor for the utility pole as well as cable wires were also observed in these areas. This is considered trash debris/unused equipment and requires removal.		
Corrective Action:	Comply with Rule 603.f.	Date:	04/30/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
	WELLHEAD			
Comment:	Inspection #696201101 documented stained soils along areas adjacent to the wellhead, and required Operator to comply with Rule 907.e and properly dispose of oily waste by 4/1/2020.  Observed stained soils have not been removed or cleaned. This corrective action remains applicable.			
Corrective Action:	Properly dispose of oily waste in accordance with 907.e.			Date: 04/01/2020

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 229646 Type: WELL API Number: 103-07303 Status: PR Insp. Status: RI**Producing Well**Comment: [Active well, IR/SW inspection.](#)

[It was observed in FIR #696201101 that the well appeared to be venting from an open valve on equipment attached to the bradenhead. It was also noted that the Operator has an approved Form 4 to vent/flare \(Doc. No. 2303395, submitted 3/29/2017, approved 12/20/2018\), and that Operator does not appear to be complying with COAs.](#)

[It was observed in this inspection that the valve appears to have been closed, and that venting no longer appears to be occurring.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696201101 documented various fluids/chemicals within the containment cellar at the wellhead, as well as on the wellhead/casing and grate. Inspection required Operator to comply with Rule 1002.f and remove fluids/chemicals within containment, and ensure equipment is maintained per Rule 605.d.  
It was observed in this inspection that the observed fluids/chemicals within the containment cellar have not been removed per corrective actions; Corrective action remains applicable.

Corrective Action: Comply with Rule 1002.f and remove fluids/chemicals within containment, and ensure equipment is maintained in good mechanical condition per Rule 605.d.

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
COGCC Operator records indicate email contact for the principal agent to be "hayespetro@centurytel.net"; it was noted that there are other inspections in the well file that appear to be being submitted to "hayespetroleum@gmail.com".  After internal review, it appears as though the email contact "hayespetro@centurytel.net" may no longer be in use by the Operator.  If the email "hayespetro@centurytel.net" is no longer the designated email contact for the Operator/Principal agent, then Operator needs to submit the required Form 1A to update contact records.  Any previous inspections submitted to "hayespetro@centurytel.net" with corrective actions and potential enforcement actions will remain applicable as it is the Operator's responsibility to immediately report changes to agent information in accordance with Rule 302.b.	trujilloam	03/31/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696201119	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5111524">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5111524</a>