

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/31/2020

Submitted Date:

03/31/2020

Document Number:

699501041

**FIELD INSPECTION FORM**

Loc ID 423992 Inspector Name: MEDINA, JUSTIN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423991	WELL	PR	12/01/2018	OW	123-33826	ROWE 13N-27HZ	PR
432559	TANK BATTERY	AC	06/30/2011		-	ROWE 13N-27HZ	AC

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Type: Ancillary equipment	# 3	Comment: automation	Corrective Action:	Date:	
Type: Horizontal Heated Separator	# 1	Comment:	Corrective Action:	Date:	
Type: Bradenhead	# 1	Comment:	Corrective Action:	Date:	
Type: Prime Mover	# 1	Comment: propane motor	Corrective Action:	Date:	
Type: Emission Control Device	# 2	Comment:	Corrective Action:	Date:	
Type: Bird Protectors	# 3	Comment:	Corrective Action:	Date:	
Type: Gas Meter Run	# 1	Comment:	Corrective Action:	Date:	
Type: Pump Jack	# 1	Comment:	Corrective Action:	Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	200 BBLS	PBV FIBERGLASS		,

Comment:	1 tank is behind pump jack with the exhaust from the pump jack motor entering the tank.	
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tnks / adequate			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 423991 Type: WELL API Number: 123-33826 Status: PR Insp. Status: PR

Facility ID: 432559 Type: TANK API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment:	<u>PR</u>	
Corrective Action:		Date:

**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection perception of location may have been distorted due to weather conditions.	medinaj	03/31/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501042	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5111648">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5111648</a>