

Inspection Photos

Location Name: AP 12-05 FOLLOWUP CA DATE 4-30-20

API#: 05-071-06170

INSP. #: 695102494



Colorado Oil & Gas Conservation Commission
37.10197, -104.95522, 2567.0m, 66°
2020/03/31 15:48:45



Colorado Oil & Gas Conservation Commission
37.10189, -104.9548, 2559.0m, 4°
2020/03/31 15:49:04

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: AP 12-05 FOLLOWUP CA DATE 4-30-20

API#: 05-071-06170

INSP. #: 695102494



PHOTO 3: AREA OF IMPACTED SOIL AROUND COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-30-20.

PHOTO 4: AREA OF IMPACTED SOIL AROUND COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-30-20.

Inspection Photos

Location Name: AP 12-05 FOLLOWUP CA DATE 4-30-20

API#: 05-071-06170

INSP. #: 695102494



PHOTO 5: AREA OF IMPACTED UNDER COMPRESSOR SKID DRAIN APPEARS THAT SKID IS BEING DRAINED ON THE GROUND. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-30-20.

Inspection Photos

Location Name: AP 12-05 FOLLOWUP CA DATE 4-30-20

API#: 05-071-06170

INSP. #: 695102494



**PHOTO 6: STANDING OIL IN COMPRESSOR SKID.
COMPLY WITH GENERAL PERSIVIONS OF THE OIL
AND GAS ACT AND SB-181 REGARDING WILDLIFE
PROTECTION. CA DATE 4-30-20.**

**PHOTO 7: STANDING OIL IN MANIFOLD ON COMPRESSOR
MOTOR. COMPLY WITH GENERAL PERSIVIONS OF THE OIL
AND GAS ACT AND SB-181 REGARDING WILDLIFE
PROTECTION. CA DATE 4-30-20.**