

Inspection Photos

Location Name: AP 12-06 CA DATE 4-30-20

API#: 05-071-08388

INSP. #: 695102496



Colorado Oil & Gas Conservation Commission
37.1003, -104.94888, 2455.0m, 316°
2020/03/31 16:15:20



Colorado Oil & Gas Conservation Commission
37.10033, -104.94893, 2457.0m, 285°
2020/03/31 16:15:46

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: AP 12-06 CA DATE 4-30-20

API#: 05-071-08388

INSP. #: 695102496



PHOTO 3: AREA OF IMPACTED SOIL APPEARS TO BE FROM DRAINING COMPRESSOR SKID ON THE GROUND. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-30-20.

PHOTO 4: AREA OF IMPACTED SOIL BETWEEN WELLHEAD AND METER HOUSE. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-30-20.

Inspection Photos

Location Name: AP 12-06 CA DATE 4-30-20

API#: 05-071-08388

INSP. #: 695102496



**PHOTO5: STANDING OIL IN COMPRESSOR SKID
CONTAINMENT APPEARS THE ENGINE OIL IS BEING
DRAINED INTO SKID. Comply with general
provisions of the oil and gas act for wildlife
protection. CA DATE 4-30-20.**