

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/31/2020

Submitted Date:

03/31/2020

Document Number:

689704475

**FIELD INSPECTION FORM**

Loc ID 335824 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 11 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281919	WELL	PR	04/03/2007	GW	045-11570	N.PARACHUTE EF08B C27A 595	PR
281923	WELL	PR	04/03/2007	GW	045-11575	N. PARACHUTE EF09D C27A 595	PR
281924	WELL	PR	04/03/2007	GW	045-11576	N.PARACHUTE EF 16B C27A 595	PR
281930	WELL	PR	04/03/2007	GW	045-11577	N.PARACHUTE EF06B C27A 595	PR
281931	WELL	PR	04/03/2007	GW	045-11578	N.PARACHUTE EF 10B C27A 595	PR
281933	WELL	PR	04/03/2007	GW	045-11579	N.PARACHUTE EF 16D C27A 595	PR
281935	WELL	PR	04/03/2007	GW	045-11580	N.PARACHUTE EF01B C27A 595	PR
281936	WELL	PR	04/03/2007	GW	045-11581	N.PARACHUTE EF07B C27A 595	PR

**General Comment:**

Follow Up Field inspection  
On 03/31/2020 at approximately 1330 hours, I, Inspector Mike Longworth, conducted a follow up field inspection at N.PARACHUTE-65S95W 27NENW at Location # 335824 in Garfield County, Colorado  
All corrective actions have been addressed from 01/03/2019 Inspection # 689702346

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<a href="#">911</a> <a href="#">Access road CR 215</a>		
Corrective Action:			Date:

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:			
Corrective Action:			Date:
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No


Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)	80 bbl				
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	281919	Type:	WELL	API Number:	045-11570	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	281923	Type:	WELL	API Number:	045-11575	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	281924	Type:	WELL	API Number:	045-11576	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	281930	Type:	WELL	API Number:	045-11577	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	281931	Type:	WELL	API Number:	045-11578	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	281933	Type:	WELL	API Number:	045-11579	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	281935	Type:	WELL	API Number:	045-11580	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	281936	Type:	WELL	API Number:	045-11581	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				



**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Gravel	Pass					
				Material Handling And Spill Prevention	Pass	
		Ditches	Pass			
		Compaction	Pass			
Check Dams	Pass					
Compaction	Pass					
		Culverts	Pass			
		Gravel	Pass			
Ditches	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704476	Inspection 689704475 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5112047">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5112047</a>