

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/31/2020

Submitted Date:

04/01/2020

Document Number:

700400786

FIELD INSPECTION FORM

Loc ID 398059 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 74740

Name of Operator: RIO MESA RESOURCES INC

Address: P.O. BOX 984

City: RANGELY State: CO Zip: 81648

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Trujillo, Aaron		aaron.trujillo@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Hayes, Mike	970-620-2257	hayespetroleum@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231047	WELL	PA	05/18/2004	SI	103-08716	GETTY-AMOCO 31	PA

General Comment:

[COGCC Inspection Report Summary.](#)

On 3-31-2020 at approximately 11:30, inspector Rick Moran, conducted a follow up inspection at Rio Mesa Resources well Getty Amoco 31 in Rio Blanco county of FIR document 666201103 dated 3-17-2020.

The purpose of the inspection done on 3-31-2020 was to measure the gas rate leaking from this P&A well. It was found a 3 cubic foot bag filled 2/3 full in 65 minutes.

This is a summary of inspection report 700400786.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Well name on P&A marker.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	Gas leaking from top of casing cement. A 3 cubic foot bag filled 2/3 full in 65 minutes.		
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 231047 Type: WELL API Number: 103-08716 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700400787	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5112154