

Inspection Photos
Operator: BP America
API#: 067-09101
Date: 3/31/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing, largely with non-native grasses such as crested wheatgrass and intermediate wheatgrass. Final reclamation will need to be comprised of seed mix more similar to reference area.



Photo 3. View of reference area vegetation, comprised of irrigated grass field. Grasses are not in identifiable condition at this time.