

# *Inspection Photos*

*Loc#3345744*

*Operator: Terra*

*Inspection #: 692402036*

*Inspection Date: 3/24/20*





Photo#1:  
Overview of Location to South.

March 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Federal DOE Loc#3345744



Photo#2:  
Views over Location to North

March 24, 2020



**Photo#3:**  
BMP at North end of site needing maintenance.



**Photo#4:**  
Anchor, no longer in use, noted Northwest  
of access road entry.

March 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Federal DOE Loc#3345744



Photo#5:  
Cut slope along older, NE portion of site.



Photo#6:  
Cut slope along older, NE portion of site.

March 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Federal DOE Loc#3345744



Photo#7:  
Cut slope along Southeast, expansion area of  
site.

March 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#8:  
Cut slope along Southeast, expansion area of  
site.

Inspection Photos: Terra Federal DOE Loc#3345744



Photo#9:  
Well line up; view Southeast to Cut slope.

March 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Federal DOE Loc#3345744



Photo#10:  
View West from Cut slope, over Wells; showing  
trench/ditch leading away from Wells > Photo#11.



Photo#11:  
Trench/ditch continues Southeasterly along Cut  
slope > Photo#12.

March 24, 2020



Photo#12:  
Trench/ditch continues Southeasterly along Cut  
slope > Photo#13.

March 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources




Photo#13:  
Looking back to Photo#12. Point where trench/ditch  
is blocked. Appears to have continued > Photo#14.

Inspection Photos: Terra Federal DOE Loc#3345744



Photo#14:  
Apparent receiving BMP from previous Photos. Insert shows point of discharge/outflow, > Photo#15.



Photo#15:  
Flexible drain conveying stormwater to base of fill slope and access road below,> Photo#16.

March 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Federal DOE Loc#3345744



Photo#16:  
Flexible drain to convey stormwater from pad above  
and BMP in Photo#14.



Photo#17:  
Flexible drain discharge point into access road  
ditch.

March 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Federal DOE Loc#3345744



Photo#18:  
View down access road, leaving Location.



Photo#19:  
View up fill slope from access road to retaining structure.

March 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Federal DOE Loc#3345744



Photo#20:  
BMP failures along access road.

March 24, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Federal DOE Loc#3345744