

Inspection Photos  
Operator: BP America  
API#: 067-08673  
Date: 3/31/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward.



Photo 3. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing here with grasses such as smooth brome and crested wheatgrass.



Photo 4. View of area along the access road where water is ponding and deep mud is resulting in expansion of road disturbance and rutting.



Photo 5. View of reference area vegetation within an open grass field, in a grazed condition. Grass species are not identifiable at this time.