

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/01/2020

Submitted Date:

04/01/2020

Document Number:

699301288

FIELD INSPECTION FORMLoc ID 437845 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 1801 CALIFORNIA STREET #2500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

25 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437836	WELL	PR	05/01/2018	OW	123-39723	Dale 4E-20H-O264	PR
437837	WELL	PR	03/15/2015	OW	123-39724	Dale 4B-20H-O264	PR
437838	WELL	PR	12/01/2018	OW	123-39725	Dale 4H-20H-O264	PR
437839	WELL	PR	12/01/2018	OW	123-39726	Dale 4G-20H-O264	PR
437840	WELL	PR	01/01/2019	OW	123-39727	Dale 4I-20H-O264	PR
437841	WELL	PR	05/01/2018	OW	123-39728	Dale 4C-20H-O264	PR
437842	WELL	PR	01/01/2019	OW	123-39729	Dale 4J-20H-O264	PR
437843	WELL	PR	11/01/2018	OW	123-39730	Dale 4D-20H-O264	PR
437844	WELL	PR	12/01/2018	OW	123-39731	Dale 4F-20H-O264	PR
437849	WELL	PR	08/01/2019	OW	123-39733	Dale 4K-20H-O264	PR
437856	WELL	PR	03/15/2015	OW	123-39738	Dale 4A-20H-O264	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate x 11		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	chain link		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	shares fencing with ignitor combustor		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	chainlink		
Corrective Action:		Date:	

Equipment:

Type: Pig Station	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 11		

Comment: all appear to be plumbed to surface		Date:
Corrective Action:		Date:
Type: Prime Mover	# 4	
Comment: Electric powered hydraulic pumps		
Corrective Action:		Date:
Type: Ancillary equipment	# 16	
Comment: Electric panel transformer, automation		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 5	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 9	
Comment:		
Corrective Action:		Date:
Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 14	
Comment:		
Corrective Action:		Date:
Type: Other	# 11	
Comment: Hydraulic lift system		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	6	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity) 250 bbl	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares containment with condensate tanks				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	10	500 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	437836	Type:	WELL	API Number:	123-39723	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	437837	Type:	WELL	API Number:	123-39724	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	437838	Type:	WELL	API Number:	123-39725	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	437839	Type:	WELL	API Number:	123-39726	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	437840	Type:	WELL	API Number:	123-39727	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	437841	Type:	WELL	API Number:	123-39728	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	437842	Type:	WELL	API Number:	123-39729	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	437843	Type:	WELL	API Number:	123-39730	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Facility ID: 437844 Type: WELL API Number: 123-39731 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

Facility ID: 437849 Type: WELL API Number: 123-39733 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

Facility ID: 437856 Type: WELL API Number: 123-39738 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 04/01/2020 at approximately 1110 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Crestone Peak Resources location:</p> <p style="text-align: right;">Dale 20H-O264 at</p> <p>Location # 437845 in Weld County Colorado. While there, I observed a producing multi well wellsite and tank battery. During this inspection no compliance issues were observed: See attached photos. Location is dry, weather is clear/partly cloudy. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	04/01/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301290	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5112893
699301291	TB pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5112894