

Inspection Photos

Operator: Hilcorp Energy
API#: 067-09086
Date: 4/3/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Vegetation is grazed and in early season condition. Bunch grasses similar to reference area observed.



Photo 3. View of reference area vegetation comprised of grazed grass field, largely in a dormant condition with perennial bunch grasses.