

Inspection Photos

Operator: Hilcorp Energy
API#: 067-08759
Date: 4/3/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Vegetation is comprised of bunchgrasses such as crested wheatgrass and shrubby fourwing saltbush.



Photo 3. View of area where vegetation is damaged from vehicle tracking in the eastern project area.



Photo 4. View of reference area vegetation comprised of sagebrush shrubland and pinyon juniper woodland.