

Inspection Photos
Location Name: Hall #1
API: 05-067-05343



Taylor Hall #1 location photo.



55 gal. drums left on location. Steel drums are empty.

Inspection Photos
Location Name: Hall #1
API: 05-067-05343



Hall #1 pump jack and electric prime mover.



Hall #1 well head.

Inspection Photos
Location Name: Hall #1
API: 05-067-05343



Taylor Hall #1 tank battery.



Compromised liner on secondary containment berm.