

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2020

Submitted Date:

03/30/2020

Document Number:

699800812**FIELD INSPECTION FORM**
 Loc ID 334142 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:21 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283724	WELL	PR	05/19/2007	GW	077-09029	FIVE R 15-1 (D14OU)	PR
283725	WELL	PR	03/09/2006	GW	077-09028	FIVE R 14-3 (D14OU)	PR
283726	WELL	SI	08/01/2019	GW	077-09027	FIVE R 11-13 (D14OU)	SI
283727	WELL	PR	05/01/2011	GW	077-09030	FIVE R 14-4 (D14OU)	PR
287193	WELL	PR	08/01/2007	GW	077-09159	FIVE R FEDERAL 14-5 (D14OU)	PR
421238	WELL	PR	06/19/2012	GW	077-10146	ORCHARD UNIT 15-12H (D14OU)	PR
421554	WELL	PR	06/19/2012	GW	077-10149	ORCHARD UNIT 23-10HM (D14OU)	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 3/30/20 at approximately 13:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at CAERUS PICEANCE LLC ORCHARD UNIT /15-12H2 (D14OU), Location #334142 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: 500 gallon methanol tank missing operator's name. See photo #0872 with a corrective action date of 5/30/20. Multiple place with unused equipment on location. See photo #0869 and #0870 with a corrective action date of 4/6/20. Oily fluid in Methanol tank containment. See photo #0871 with a corrective action date of 4/6/20.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Type	TANK LABELS/PLACARDS			
Comment:	500 gallon methanol tank missing operators name. See photo #0872			
Corrective Action:	All tanks with a capacity of ten (10) barrels or greater shall be labeled with name of operator. Properly label tank.		Date:	05/30/2020
Type	CONTAINERS			
Comment:	Chemical tank			
Corrective Action:			Date:	
Type	BATTERY			
Comment:				
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	911			
Corrective Action:			Date:	
Good Housekeeping:				
Type	OTHER			
Comment:	Oily fluid in Methanol tank containment. See photo #0871			
Corrective Action:	Production facilities, shall be kept free of waste materials. Remove and dispose of waste materials from location.		Date:	04/06/2020
Type	UNUSED EQUIPMENT			
Comment:	Multiple place with unused equipment on location. See photo #0869 and #0870			
Corrective Action:	Production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove unused equipment from location.		Date:	04/06/2020
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	Barbed wire fence around location			

Corrective Action:		Date:	
Equipment:		corrective date	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: Chemical tank at wellhead			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment: Line heater			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,

Comment:	500 gallon capacity				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Separate containment				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,

Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	HEATED STEEL AST		,

Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Centralized containment					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	283724	Type:	WELL	API Number:	077-09029	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	283725	Type:	WELL	API Number:	077-09028	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	283726	Type:	WELL	API Number:	077-09027	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:	<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:	Last produced July 2019								
Corrective Action:						Date:			
Facility ID:	283727	Type:	WELL	API Number:	077-09030	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	287193	Type:	WELL	API Number:	077-09159	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	421238	Type:	WELL	API Number:	077-10146	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	421554	Type:	WELL	API Number:	077-10149	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Culverts				
Culverts						
		Ditches				
		Gravel				
		Compaction				
Berms						
Gravel						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402357294	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5110670
699800813	Photos for Insp. #699800812	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5110667