

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/06/2020

Submitted Date:

04/06/2020

Document Number:

695102515**FIELD INSPECTION FORM**Loc ID 307467 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1801 BROADWAY SUITE 350City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217701	WELL	PR	12/04/2003	GW	071-06480	APODACA 33-29	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 4: UNUSED 1" RISER NOT LO/TO.		
Corrective Action:	24 HOURS TO LO/TO 30 DAYS TO REMOVE RISER PER RULE 603.f.		Date: <u>04/07/2020</u>
Type	OTHER		
Comment:	PHOTO 5: AREA OF IMPACTED SOIL NEAR WELLHEAD APPEARS TO BE COMING FROM OIL RUNNING OFF PUMPJACK BASE. PHOTO 6: AREA OF IMPACTED SOIL NEAR PUMPJACK PRIME MOVER APPEARS TO BE COMING FROM OIL PUMPJACK PRIME MOVER LEAKS. PHOTO 7: AREA OF IMPACTED SOIL NEAR PUMPJACK PRIME MOVER ON THE OPPOSITE SIDE FROM PREVIOUS PHOTOS APPEARS TO BE COMING FROM OIL PUMPJACK PRIME MOVER LEAKS.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. PER RULE 1002.f.(2).D		Date: <u>05/06/2020</u>

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	IS NOT PLUMBED TO SURFACE		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	PHOTO 8: PUMPJACK PRIME MOVER IS SATURATED WITH WHAT APPEARS TO BE OIL.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: <u>05/06/2020</u>

Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 217701 Type: WELL API Number: 071-06480 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695102516	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5116819