

# Inspection Photos

4/06/2020

Operator: CAERUS PICEANCE LLC

Location ID: 335922

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC  
Location ID: 335922



**Photo 1:** Photo shows the three (3) active wells on the Location. Records show well have produced since 2009.



**Photo 2:** Photo taken from the north end of the Location, facing northeast. Photos 2-6 provide an overview of the Location from northeast, east, southeast, south, southwest to west. Photos show large areas of the current pad that do not appear to be necessary for production activities, and require reclamation.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC  
Location ID: 335922



**Photo 3:** See comments under photo 2.



**Photo 4:** See comments under photo 2.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC  
Location ID: 335922



**Photo 5:** See comments under photo 2.



**Photo 6:** See comments under photo 2.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC  
Location ID: 335922



**Photo 7:** Photo taken from the northeast corner of the pad, facing south. Photos 7-9 provide an overview of the location from south, southwest to west. Photos show large areas of the current pad that do not appear to be necessary for production activities, and require reclamation.



**Photo 8:** See comments under photo 7.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC  
Location ID: 335922



**Photo 9:** See comments under photo 7.



**Photo 10:** Photo taken from the southwest corner of the pad, facing east. Photo shows topsoil stockpile. Vegetation observed on the soil stockpile were predominantly undesirable weedy plant species such as *Bromus tectorum* in violation of Rule 1002.c



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC  
Location ID: 335922



**Photo 11:** Photo taken from the southeast corner of the pad, facing southwest. Photos 11-13 provide an overview of the Location from southwest, west, to northwest. Photos show large areas of the current pad that do not appear to be necessary for production activities, and require reclamation.



**Photo 12:** See comments under photo 11.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC  
Location ID: 335922



**Photo 13:** See comments under photo 11.



**Photo 14:** Photo taken from the south end of the pad facing west. Photos 14- 18 provide an overview of the Location from west, northwest, north, northeast to east. Photos show large areas of the current pad that do not appear to be necessary for production activities, and require reclamation.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC  
Location ID: 335922



**Photo 15:** See comments under photo 14.



**Photo 16:** See comments under photo 14.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC  
Location ID: 335922



**Photo 17:** See comments under photo 14.




**Photo 18:** See comments under photo 14. Photo also shows fill areas of the Location that will require contouring and regrading to the former topography.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC  
Location ID: 335922



**Photo 19:** Photo taken from the southwest corner of the Location. Photo shows unused equipment (rock socks, pipe) being stored on the Location. Equipment/materials require removal and proper storage in accordance with 603.f



**Photo 20:** Photo of sign at Location entrance.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC  
Location ID: 335922



**Photo 21:** 2016 Google Earth Aerial imagery; most current available google earth imagery. Photo shows large areas (~1.8 acres) of the current production area that do not appear to be necessary for production activities, and require reclamation in accordance with Rule 1003.b.