



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type PUMP JACK

Comment: 4' barb wire

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Prime Mover # 1

Comment: electric motor

Corrective Action:

Date:

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment # 2

Comment: electric

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 241089 Type: WELL API Number: 123-08877 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection perception of location may have been distorted due to weather conditions.	medinaj	04/02/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501063	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5117578">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5117578</a>