

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W/23SWNW

Location ID: 312610



Photo #0917 from entrance to location



Photo #0921 Tank NFPA label weathered and not legible.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W/23SWNW

Location ID: 312610



Photo #0920 Multiple places with unused equipment on location.



Photo #0918 Debris on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W/23SWNW

Location ID: 312610



Photo #0922 Unmarked deadman.



Photo #0923 Unmarked deadman.