

Inspection Photos
Operator: BP America
API#: 067-07014
Date: 4/3/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Vegetation is grazed and in a condition similar to surrounding reference area.



Photo 3. View of the southern project area from the southeastern edge facing westward. Irrigation ditch runs adjacent to southern edge of working area.




Photo 4. View of musk thistles within the project area.



Photo 5. View of reference area vegetation, comprised of irrigated grass field, largely in grazed condition.