

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/07/2020

Submitted Date:

04/07/2020

Document Number:

696102681**FIELD INSPECTION FORM**Loc ID 438901 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438898	WELL	PR	08/01/2019	OW	123-40195	North Platte Federal 11-14-22HNC	PR
438899	WELL	PR	07/14/2015	OW	123-40196	North Platte Federal A11-E14-22HNB	PR
438900	WELL	PR	07/31/2015	OW	123-40197	North Platte Federal A-E-22HC	PR
438902	WELL	PR	08/14/2015	OW	123-40198	North Platte Federal F-J-22HNC	PR
438903	WELL	PR	07/23/2015	OW	123-40199	North Platte Federal F11-J14-22HNB	PR
438904	WELL	PR	08/23/2015	OW	123-40200	North Platte Federal F21-J24-22HNB	PR

General Comment:

This is a WELL inspection.
Well(s): 6: Producing | PR.
Battery: Active.

Centralized Battery serves 2 Location ID (433629, 438901).
(Well(s): 13: Producing | PR).

Refer to Field Inspection Report doc. #696102679 and/or Location ID #433629
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	6: Wellsites		
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696102679 and/or Location ID #433629 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		
	Date:		

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:	Refer to Field Inspection Report doc. #696102679 and/or Location ID #433629 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	6: Wellsites ; Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 6		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696102679 and/or Location ID #433629 for Battery / Facility, Equipment info.		

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.391527,-104.422185	
Comment:	Centralized Battery serves 2 Location ID (433629, 438901).					
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	438898	Type:	WELL	API Number:	123-40195	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			
Facility ID:	438899	Type:	WELL	API Number:	123-40196	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			
Facility ID:	438900	Type:	WELL	API Number:	123-40197	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			
Facility ID:	438902	Type:	WELL	API Number:	123-40198	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			
Facility ID:	438903	Type:	WELL	API Number:	123-40199	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			
Facility ID:	438904	Type:	WELL	API Number:	123-40200	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			
COGCC Comments									

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 04/07/2020 at approximately 13:40 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte /F-22 Location ID: 438901 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 6: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 2 Location ID (433629, 438901). (Well(s): 13: Producing PR).</p> <p>Refer to Field Inspection Report doc. #696102679 and/or Location ID #433629 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/07/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696102682	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5117725