

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/07/2020

Submitted Date:

04/07/2020

Document Number:

700700423**FIELD INSPECTION FORM**

Loc ID 323942 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:19 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211320	WELL	PR	09/10/1997	GW	045-07080	YOUBERG RU 22-7	PR
445633	WELL	PR	11/21/2016	OW	045-23128	Youberg RU 512-7	PR
445634	WELL	PR	11/28/2016	OW	045-23129	Youberg RU 523-7	PR
445635	WELL	PR	11/22/2016	OW	045-23130	Youberg RU 31-7	PR
445636	WELL	PR	11/28/2016	OW	045-23131	Youberg RU 423-7	PR
445637	WELL	PR	11/21/2016	OW	045-23132	Youberg RU 322-7	PR
445638	WELL	PR	10/01/2016	OW	045-23133	Youberg RU 323-7	PR
445639	WELL	PR	11/22/2016	OW	045-23134	Youberg RU 321-7	PR
446083	WELL	PR	10/01/2016	OW	045-23230	Youberg RU 412-7	PR
446084	WELL	PR	10/24/2016	OW	045-23231	Youberg RU 422-7	PR
446085	WELL	PR	09/26/2016	OW	045-23232	Youberg RU 23-7	PR
446086	WELL	PR	11/21/2016	OW	045-23233	Youberg RU 421-7	PR
446087	WELL	PR	11/21/2016	OW	045-23234	Youberg RU 411-7	PR
446088	WELL	PR	11/22/2016	OW	045-23235	Youberg RU 311-7	PR

General Comment:

COGCC Inspection Report Summary

On Tuesday 4/7/20 at approximately 10:30 AM, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RU 22-7, at Location # 323942 in Garfield Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed:

- Secondary containment around 80 BBL tank inadequate.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Type	TANK BATTERY				
Comment:					
Corrective Action:				Date:	

Equipment:					corrective date
Type: Horizontal Heated Separator	# 14				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	# 14				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 8				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 5				
Comment:	chemical tanks				
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:	80 bbl tank					
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment: Inadequate berms around tank					
Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).					Date: 05/05/2020

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211320	Type:	WELL	API Number:	045-07080	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	445633	Type:	WELL	API Number:	045-23128	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	445634	Type:	WELL	API Number:	045-23129	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	445635	Type:	WELL	API Number:	045-23130	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	445636	Type:	WELL	API Number:	045-23131	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	445637	Type:	WELL	API Number:	045-23132	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	445638	Type:	WELL	API Number:	045-23133	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	445639	Type:	WELL	API Number:	045-23134	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Facility ID:	446083	Type:	WELL	API Number:	045-23230	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	446084	Type:	WELL	API Number:	045-23231	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	446085	Type:	WELL	API Number:	045-23232	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	446086	Type:	WELL	API Number:	045-23233	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	446087	Type:	WELL	API Number:	045-23234	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	446088	Type:	WELL	API Number:	045-23235	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Berms				
		Ditches				
Ditches		Check Dams				
		Gravel				
Gravel		Culverts				
		Sediment Traps				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700428	Photos for RU 22-7	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5117803