

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 426586 Type: WELL API Number: 123-34733 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
<p>This is a follow up for previous inspection DOC#: 679602124. All corrective actions assigned in previous inspection DOC#: 679602124 has been resolved. No new corrective actions were observed at the time of inspection. Risers are LO/TO for future use. Review my inspection, photos and previous inspection DCO#: 679602124 for additional information on this location.</p> <p>**Weather Conditions: overcast, dry ground</p>	santistb	04/08/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679602453	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5118736