

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/08/2020

Submitted Date:

04/08/2020

Document Number:

693502643

FIELD INSPECTION FORM

Loc ID 318577 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
	303-825-4822	cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241641	WELL	SI	12/01/2019	OW	123-09430	UPRR 43 PAN AM B 10	PR

General Comment:

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign is adeqate at time of inspection but is starting to fade and will need to be replaced in near future.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	mesh		
Corrective Action:			Date:
Equipment:			
Type: Prime Mover			# 1
Comment:	Electric motor		
Corrective Action:			Date:
Type: Pump Jack			#
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment			# 1
Comment: Electric pane with meter			
Corrective Action:			Date:
Type: Bradenhead			# 1
Comment: Appears to be plumbed to surface			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 241641 Type: WELL API Number: 123-09430 Status: SI Insp. Status: PR

Producing Well

Comment: Valves on well head appear to be in the open position.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<u>Routine inspection</u>	silverr	04/08/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693502644	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5119076