

# Inspection Photos

Location Name:

Two E Ranches 1 & Aloysius C34-32D

Location ID: 317659



Photo #1 Well & Sign

Photo #2 Well & Sign

## Inspection Photos

Location Name:

Two E Ranches 1 & Aloysius C34-32D

Location ID: 317659



**Photo #3 Lubricator plunger catcher is leaking**

**Photo #4 fluid on surface casing from leak**